25X1A

25**X**1A

TO:

Approved For Release 2002/07/30 : CIA-RDP75B00285B000300180011-8

· CORRECTION OF THE RECTION OF THE PROPERTY OF

SUBJECT: Maximum Emergency DATE: October 23, 1962
Temperature

Reference: Your letter dated 10-15-52

Our normal Indoctrination Program had been established to expose subjects to a 500°F wall temperature for a period of fifteen minutes after stabilization. This has resulted in some subjects being exposed to this maximum temperature range for as long as twenty minutes due to the build-up time experienced.

As a result of these tests with our latest subjects, we have experienced deformation of the sun visor, plus some deformation of the helmet.

Due to the sun visor deformation we have changed the configuration to a sacrifice type unit for easily discarding same.

On our last run we maintained a wall temperature of 450°F for five minutes with no apparent helmet damage.

The ambient air temperature at the helmet reached 280°F. All vent was off.

At no time did the subjects claim to be unbearably hot; somewhat uncomfortable, but still able to proceed with some limited activity for an undetermined time.

It was for this reason that we requested a more definite number for the emergency temperature that could be expected.

Our current plans are to our the tests at +00°F maximum wall temperature for five minutes unless another temperature is provided.

This will not cause us to damage any helmets and still expose the subjects to a high heat emergency condition.

25X1A

Project Manager

25X1A

To:	
FROM:	

PATE! OCTIS, ME


AS I HAVE SUGGESTED. TO

X1A

SINCE WE CANNOT

GIVE YOU A MAXIMUM EMERGENCY
TEMPERATURE, IT WILL BE OF INTEREST
TO KNOW WHAT MAXIMUM TEMPERATURE
CAN BE TOLERATED BY THE SUIT AND
CREW MEMBER.

I WOULD SUGGEST THAT THE DATA BE COMPILED AS FOLLOWS:



25X1A

September 19, 1962

	MI management of
Bubject:	Final color scheme for our Parachute Canoples
Dear	
program The	final color scheme of the parachute canopies for our has been resolved. first stage canopy will be all white. The main canopy colored as follows: Blow out cap - White Top Section 2.2 oz. material - White Remainder - Three equal radial sections of white, only drab and orange Suspension Lines Main Canopy - Olive drab
A	future deliveries should be made to this configuration me two (2) copies of your drawing on this item.
any Forward	
Ang Forward	Very truly yours,

Approved For Release 2002/07/30 : CIA-RDP75B00225R000300180011-8 AM-462

25X1A	TO: PROM: 2 DATE: August 15, 1962	5X1A
	Dear Harry,	
	Just a reminder that we require the parachute	
	color required for production hardware. This will	
	apply both to the first and second stage parachutes.	
	I am holding up production of the canopies pending	
	a decision on color and the final material planned	
	for the main canopy.	
	Congratulations on the success at El Centro.	
	I wish I had been able to be on the ground to greet	
	you.	
	Yours truly,	
	2	5X1A

ACB/s

March 13, 1962

25X1A

Dear Ed,

25X1A

25X1A

25X1A

As discussed in our telephone conversations the past two days, we would like ______ to build 8 additional 35 foot main canopies. These canopies will be used on the test program being conducted at El Centro. Four canopies are to have standard 1.1 ounce fabric throughout; four canopies to have 2.25 ounce fabric in the top portion (approximately 27" down from vent), all else to be standard 1.1 ounce.

Both styles of canopies are to include the puckered vent, heavier bridle and the pilot chute will be strengthened to retain the spring. Also, if practical, the cuarter bags will be revised to include the gussets requested by

25X1A

As we discussed yesterday relayed information to effect that the main lift web had been weakened by about 3,000 relayed information to the 25X1A pounds when the grommets were installed on the packs shipped in the past two/weeks. These grommets and their location were requested by | in ah/attempt to simplify and smooth out the rear surfaces of the pack. As has been reported to me, he specifically requested one at each of the top corners of the mechanical pans where the main lift web crosses the edge of the reported that simulating this condition repan. duced the tensile strength of the same type webbing from 8400 pounds without grommets to 5400 pounds with grommets. the test jumpers at El Centro have refused to jump with the 2 packs made with the grommet holes so located. The first two operational packs have the same condition. Please make four more packs which will replace the four units mentioned. These will be packs only -- no canopies will be required, nor will we make new

Continued . . .

25X1A

Page -2-


March 13, 1962

pans when these packs are delivered. The canopies and pans will be switched from the existing items. These packs are to be made in the latest configuration omitting the 2 grommets at the top corners of the mechanical pans.

These 4 packs appear to be a loss we could have avoided had we been given more time to consider some of the requested changes. However, I am told that they can be used for dummy tests at El Centro.


25X1A

I have received _______letter of February 8. It was evidently mailed on from Buffalo to El Centro and has just how caught up with me. I will consult with our ______ to determine steps 25X1A he wishes us to follow in revising the contractual coverage on this program.



25X1A

25X1A



		November 28,	1961
		1	
Attention:	4		
Dear Ed:			
quantities ag	in several telephone reed upon in the me We have had no ss:	eting at Firewel	November 17
2 complete 4 spare di	e rigs (with 60-inches spare rigs (with 6 rogue packs (with 6 ain canoples (three	60-inch drogues) Q-inch drogues)	om the twick
12 78-inch	drogue canopies (s		tests)
50 spare	iregue pilot chutes,	deployment bags	and bridles
Firewel will			
	irogue and 6 manual apple housings	main deployment and ripcord ass	housings semblies
15 manual	drogue riser cable cable housings	housings	
A minimum o plus additiona	f 6 each of other o	cable housings will ry to support the	be supplied program.
Firewel will	also supply the man	ual cable housing	for main and

25X1A

25X1A

25X1A

Enclosed are copies of the photographs taken on November 17 which show principally the misalignment of the seat kit attach strap and the meeting harness ring.	and i	Approved For Release 2002/07/30 : CIA-RDP75B00285R000300180011-8	
which show principally the misalignment of the seat kit attach strap and the meeting harness ring. have agreed upon a reasonable solution which involves a minor change in the location and mounting of the ring on the parachute harness. 25X1A	25X1A		
25X1A lis operating under an out-dated contract which essentially does not cover you on the work done over the past year. 25X1A I discussed with the possibility of tancelling your present contract and rewriting one that gives you better coverage for the development phase of the program. I would like to have your reactions on this as well as comments from your 25X1A I believe if you read over the old purchase order, you will agree that it is somewhat outdated. We have postponed the test start date one week to December 11 to give us more time to get the someoner in shape. 25X1A about this today. 25X1A RFZ:jcc Enclosures (Rhotographs)	25X1A	which show principally the misalignment of the seat kit attach strap and the meeting harness ring. have agreed upon a reasonable solution which involves a minor change in the location and mounting of the ring	25X1A
25X1A I discussed with the possibility of tancelling your present contract and rewriting one that gives you better coverage for the development phase of the program. I would like to have your reactions on this as well as comments from your lead over the old purchase order, you will agree that it is somewhat outdated. We have postponed the test start date one week to December 11 to give us more time to get the schipment in shape 25X1A 25X1A RFZ:jcc Enclosures (Photographs)	25¥1A	ic operation under an out-dated contract which essen-	
I discussed with the possibility of tancelling your present contract and rewriting one that gives you better coverage for the development phase of the program. I would like to have your reactions on this as well as comments from your	25X IA	tially does not cover you on the work done over the past year.	
I believe if you read over the old purchase order, you will agree that it is somewhat outdated. We have postponed the test start date one week to December 11 to give us more time to get the somipment in shape. 25X1A Wery truly yours, THE FIREWEL COMPANY, INC. 25X1A RFZ:jcc Enclosures (Photographs)	25X1A	I discussed with the possibility of tancelling your present contract and rewriting one that gives you better coverage for the development phase of the program. I would like to	
you will agree that it is somewhat outdated. We have postponed the test start date one week to December 11 to give us more time to get the enginement in shape. 25X1A Very truly yours, THE FIREWEL COMPANY, INC. 25X1A RFZ:jcc Enclosures (Photographs)	25X1A	I believe if you read over the old purchase order,	
25X1A		you will agree that it is somewhat outdated.	
25X1A	,	We have postnoned the test start date one week to December	
25X1A talked to very truly yours, THE FIREWEL COMPANY, INC. 25X1A RFZ:jcc Enclosures (Photographs)		11 to give us more time to get the equipment in shape.	25X1A
THE FIREWEL COMPANY, INC. 25X1A RFZ:jcc Enclosures (Rhotographs)	25X1A	talked toabout this today.	
RFZ:jcc Enclosures (Photographs)		Wery truly yours,	
RFZijcc Enclosures (Photographs)		THE FIREWEL COMPANY, INC.	
Enclosures (Photographs)			25X1A
25V1A		RFZ:jcc //	
25X1A cc:		Enclosures (Photographs)	
	25X1A	cc:	